

به نام خدا

فرمول های حالت های مختلف تنش فون- مایز

State of Stress	Boundary Conditions	von Mises Equations
General	No restrictions	$\sigma_v = \sqrt{\frac{1}{2}[(\sigma_{11} - \sigma_{22})^2 + (\sigma_{22} - \sigma_{33})^2 + (\sigma_{33} - \sigma_{11})^2 + 6(\sigma_{12}^2 + \sigma_{23}^2 + \sigma_{31}^2)]}$
Principal stresses	$\sigma_{12} = \sigma_{31} = \sigma_{23} = 0$	$\sigma_v = \sqrt{\frac{1}{2}[(\sigma_1 - \sigma_2)^2 + (\sigma_2 - \sigma_3)^2 + (\sigma_3 - \sigma_1)^2]}$
General plane stress	$\sigma_3 = 0$ $\sigma_{31} = \sigma_{23} = 0$	$\sigma_v = \sqrt{\sigma_{11}^2 - \sigma_{11}\sigma_{22} + \sigma_{22}^2 + 3\sigma_{12}^2}$
Principal plane stress	$\sigma_3 = 0$ $\sigma_{12} = \sigma_{31} = \sigma_{23} = 0$	$\sigma_v = \sqrt{\sigma_1^2 - \sigma_1\sigma_2 + \sigma_2^2}$
Pure shear	$\sigma_1 = \sigma_2 = \sigma_3 = 0$ $\sigma_{31} = \sigma_{23} = 0$	$\sigma_v = \sqrt{3} \sigma_{12} $
Uniaxial	$\sigma_2 = \sigma_3 = 0$ $\sigma_{12} = \sigma_{31} = \sigma_{23} = 0$	$\sigma_v = \sigma_1$

معیارهای تسلیم مواد نرم در سه بعد

